
## **Smoke and Dye Testing Summary**

### **High Level Sewershed**

Run Summary ————————————————————————————————————									
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length		
S1028-071	Smoke	9/9/2008	ADS/TM	S13EE1003MH	Dry	Yes	468.62		



# **Smoke and Dye Testing Summary**

## **High Level Sewershed**

Run Summ	ary <del></del>							
Test ID Test Type		Date Inspected	Company / Super.	Blower MH		Ground Condition	Notification Made?	Total Length
S1028-071	Smoke	9/9/2008	ADS/TM	S13EE1003MH		Dry	Yes	468.62
Isolated Pi	pes ———							
Pipe ID		Upstream MH	Downstream MH		Length (ft)	Diameter (In)		
S13EE10	S13EE1003G1		S13CC1019MH		468.6154	. 2	2	

#### **Observations & Photos**

No smoke was observed during this test.